Dear fellow 1956 Golden Hawk Owners

Thank you for responding to my, ad i Turning Wheels. My name is Frank Ambrogio and currently, I'm the President of the Orlando Area Chapter of the Studebaker Drivers Club. I'm also not an expert on 1956 Golden Hawks. Although I tend to be something of a purist, I want you to be a part of our group even if you car is no longer stock in appearance or mechanics. As long as it is a 1956 Golden Hawk, that is all that matters.

My first priority will be to establish a roster of 1956 Golden Hawk owners. I want to list each owner's car(s) including serial number, engine number, body number, color, transmission type, and some options. I will update and distribute periodically. I have included a first offering of the roster in this package.

We own a unique automobile. It is the only model that truly reflects the Studebaker/Packard marriage in that it is a real Studebaker with a real Packard engine. The pre-1957 Packards were all Packard while the 1957-58 Packards were really Studebakers with a Packard name plate and some left over Packard trim. Although this makes our cars unique, this is also the source of much frustration whenever we look in our parts catalogs for an engine part and see the aggravating "except 56J" notice.

I hope this project will lead to a system of communication and mutual help where we can do things for ourselves. I am not setting any goals and by the same token I am not looking to any limits. I will gather, organize, and distribute the information you provide me. Anything else this club grows into will depend on you. Please be assured, I'm just an old car lover and I'm not doing this for any kind of profit or prestige. I do hope that in time, we will become the experts who know all the facts about these cars.

While I'm willing to do most of the work, such as compiling and distributing the information, I would like you to do one thing for me.

If you haven't already done so, you can get a copy of the original production order for your car from Newman & Altman for \$15.00. Their address is 405 West Sample Street South Bend Indiana 46621. All you need to tell them is your vehicle serial number (603____ for South Bend cars and 680___ for Los Angeles cars.) This number is located on your driver side door jamb. Most of you did not send me your engine number or body number. The model/body number is on the firewall on the passenger side and starts with 56J-K7 ___. The engine # is stamped on the boss at the top side front end of the engine block, next to the oil filler tube. It is hard to read even if you can find it, but it "should" start with S___ for automatics, and K___ for overdrives. The production order from Newman & Altman should list of this for you. If you would like to do this, and send me a copy, I can better keep track of what was original and what has been changed. I am not drumming up business for Newman & Altman, but I don't know any other way. I have attached a copy of a production order from one of my cars. I would prefer you getting the one for your car and sending me a copy, rather than asking you for some sort of dues. I would love to get the production orders for all 4071, 1956 Golden Hawks and compile my statistics, but at \$15.00 each, that is over \$60,000.

To get things started, I have listed a few questions that collectively we may be able to answer for ourselves.

- 1. Some cars have STUDEBAKER SCRIPT ON THE FENDERS. Some cars have nothing. I have seen one that says STUDEBAKER V8. Does anyone know at what point they started adding the script? Of my two cars, serial 6031884 does not have the script while serial 6032195 does. I don't know about Los Angeles produced cars. (This information is listed under "FS" on the roster.)
- 2. Our steering wheels seem it disintegrate easily. Anyone had one repaired? Who did it? Good job?
 - 3. What have you done to cure your valve lifter problems?
- 4. Any suggestions on extending the life of your Ultra-matic? I have added a transmission cooler.
- 5. Why do some cars have chrome "GOLDEN HAWK" script on the trunk and some have Gold script?

If you know of any other 1956 Golden Hawk owners please ask them to provide (prin
or type) the following information:
Name, Address, Phone#
Car serial number (South Bend cars started with 6030001, LA cars started with 6800001)
Body number (56J-K7
Engine Number (Automatics were supposed to start with S1001, Overdrives K1001)
Transmission: AD OD
Color FS PB PW

P.S. A fellow named Vito Paolantonio 320 Willow Drive Little Silver New Jersey 07739 is looking to buy a 1956 Golden Hawk. If you can help, you can call him at 201-747-6255. Frank

DATEMATION	<u> </u>	PART BURNET	FASC "	Lift-E Heb	of Girls			
1 12 CL 1 III FL	COLORE NO.	- -	POOK.	1075.		гно. 998	ESTIAL NO.	٠, ١
CITY DOMESTIC TO TO TO TO	P. 10	YRWAIR KÉVING.	FRAT ASS		JACKS NUM		6032	18
2591 3 H	4-950	5-1325		5-56	5-2	٥<٩		٠
ORIANDO FLA				20 14 (05)	T . C	, -56		
7 914	· · · · · · · · · · · · · · · · · · ·			<u>:</u>	THE STATE OF			
Charles of the August Company	سلامسه هي	_·		-			 * -	
64 K7						. '		
8417 Acha Dust	344							
ITRA TRAN								
የው ያቸልር 10 አለ - ሂ መለተ			 	<u>.</u>				
C 4749 BZ	DIR	516			_ : · -	7.	1 de 1 de 1	,
C 2738 Z	: RC 27	142 B		1.0	, ,		- A - 20	-
c 2488	NC 27	61 Z			- 1	·· ·	200	
C 2774BZ	nc 27	756B		٠.		٠		
C 2750B		٠		· · · · ·	'A;	· · · · · ·		
				<u>'</u>		. *	- 25 · 40	·
	· · ·			· .		٠.	\$ 50 g	
						- '*.	्राच्या कर्ते । इ.स.च्या	7
Engine # 50720 V- Jenitica Fey numb Date to thip Febr Sales order number Final assembly da Destination Orla PART_#QTY AC-26881	-B Der HH-950 Der H 10 Pr F 10 Att March S Ando, Flor	1990 tire numb 3. 1950 ida 21100	275 HP er 107	Hony Truni Date 5 Hacto Date Ship	cude 56 k Key Ny written ory peda shipped via Teu	iJ-K7 imber : i Febra ir numi i Marci ickawa;	Jary II, ber 3999 5 9, 1958 9 McDowal	195 E
AC-2738 h AC-2747 1 AC-2750 1 AC-2756 1 AC-2762 1 AC-2769 1 AC-2774 1	CAP and RADIO, CIGAR CLOCK BACK-U	d DISK, h "Strato! LIGHTER C KIT, elec P LAMP KI IZEP and	ob (10 ine A) Omblets Crit T - C=0 Defect	ll disk) 1 utomatic 1 E (-b TER KIT wa	15° Mawi tuning -	С-К	·	
TH417 RO 34 POWER STEERING DIRECTIONAL SIGNA 7:10 X 15 WH1!GWA	ii.g	fint	erior .	trim??)				
Color extenion F			CHIA					
	5637(U) De 5637(U) Me		(PPER)					

1956 STUDEBAKER GOLDEN HAWK - INFORMATION LIST

1956 STUDEBAKER GOLDEN HAWK (4071 PRODUCED) MODEL 56J-K7 MARCH 6, 1989 WEIGHT 3360 LBS, WHEELBASE 120-1/2", LENGTH 203-15/16", HEIGHT 56-15/16", WIDTH 70-7/16" TRANSMISSION BORG-WARNER T-85 (OVERDRIVE), PACKARD TWIN-ULTRAMATIC (AD), TIRES 7:10X15 ENGINE 352 CID PACKARD 275 HP V-8, COMP RATIO 9.5:1

SAME ENGINE USED IN 1956 PACKARD CLIPPER CUSTOM (60), LOWER POWERED SIMILAR ENGINE WAS USED ON 56 NASH AMBASSADOR, HUDSON HORNET, AND PACKARD SUPER/DELUXE CLIPPER. PACKARD USED 374 CID SAME BASIC ENGINE.

CAPACITIES: RADIATOR 25 QTS (26 W/HEATER), GAS TANK 18 GALS, TRANSMISSION 11.5 QTS (AD) DEXRON II, 3-3/4 PINTS (OD), REAL AXLE 3 QTS SAE 90 HYPOID, CRANKCASE 5 QTS, OIL BATH 1 PINT SAE 40 (OR 50)

BRAKES

FRONT WHEEL CYLINDER KIT BENDIX 66821, REAR BENDIX 66828 COOLING SYSTEM

FANBELT (GENERATOR) DAYCO 155701, (POWER STEERING) DAYCO 15501

RADIATOR HOSE LOWER DAYCO 81331/M13 (ID=1-3/4", LENGTH=16-1/2") FLEX HOSE

THERMOSTAT SEARS 78539 (OR 78541)

WATER PUMP 458410, SEALED POWER PC-152, THOMPSON FP-1175

ELECTRICAL SYSTEM

BATTERY CABLES POSITIVE 48" TRW 1-48, NEGATIVE 20" NEIHOFF 1-20 (COULD USE 16") NEGARIVE GROUND

FLASHER ECHLIN 536, DIMMER SWITCH ECHLIN DS102, HORN RELAY ECHLIN HT101, STOP LIGHT SWITCH ECHLIN SL134, FILKO SLS-24, STANDARD SLS-27

COIL 6480147, AUTO-LITE CAD-4001 (SUBSTITUTE 5-60 W/32-1 BRACKET, NEIHOFF AL179 RESISTOR 439961, AUTO-LITE PU-4001

DISTRIBUTOR 6489834, AUTO-LITE IBJ-4001-C (IBJ-4001-E UPGRADE) USE SAE 20 OIL, 3-5 DROPS POINTS NEIHOFF AL11HV, ECHLIN CS720A GAP .016", CONDENSER NEIHOFF AL31, ECHLIN AL868 DISTRIBUTOR CAP, STANDARD AL-131, ECHLIN AL-99, ROTOR BORGPWARNER D-104, ECHLIN AL65, NEIHOFF AL86

SPARK PLUGS CHAMPION RN12YC, XN12YC, N8-67B GAP = .033-.035"

GENERATOR 1540825, AUTO-LITE GJC-7002-F (SUBSTITUTE 45-721), USE SAE 20W ON OILERS VOLTAGE REGULATOR 1539541, AUTO-LITE VRX-6008A (SUBSTITUTE 8-414), ECHLIN VR206, FUSE ECHLIN VRF35

STARTER 472231, AUTO-LITE MDF-6008, NEIHOFF AL-200???

SOLENOID STANDARD SS202, STARTER DRIVE BENDIX 480082, ACCURATE 3-205, AUTO-LITE 6018 ENGINE

CARBURETOR-CARTER WCFB 2394S QUAD 1-1/4" REBUILD KIT=FILKO 24-2224A, BAILY 614259 FUEL PUMP 440629, CARTER M-2198-S OR AC 5594299 3-1/2-5 PSI, (HUDSON/NASH=AC5594293) REPAIR KIT=STUDEBAKER 6484039

OIL FILTER FRAM C4P (OR C4), WIX 51006, NAPA 1006, WALKER DELUXE WD-36, PUROLATOR P-34, AC P-209

TRANSMISSION

ALUMINUM POWER GLIDE RINGS WILL FIT ON THE ULTRA-MATIC

MISCELLANEOUS

WIPER BLADES 12"

If anyone knows of any other interchanges, let me know and I will update the list.

ITEMS OF INTEREST

In January 1987, I wrote to a man named Kenneth L. Johnsonwho claimed to have all thpes of rubber hoses. I sent him information on the 56 GH hpper and lower radiator hoses (part number 1539087 and 1539084). After MANY months, his response was that he did not have the required hoses. He also stated that he had inquired about having the hosed MADE as to correct size and diam. He had not received a reply as to the cost at that time. He said he would keep my name on file and let me know the results. I have not heard from him since.

Perhaps if all of us were to bombard Mr. Johnson, with requests for these hoses, he may decide that there may be enough profit in it to be worth the effort (assuming he is still in business.)

The address is KENNETH L. JOHNSON, CLASSIC AUTO PARTS, 550 INDUSTRIAL DRIVE, CARMEL, INDIANA 46032

Also several years ago I saw an article on converting Delco or Auto-lite distributors to Chrysler solid state ignition. If you are in to such things, you can try to reach JACK KURTZ 131 WEST STREET LAKE GENEVA WI 53147 414-248-6572.

There is a man in the Packards International Club who seems to be very knowledgeable on Ultra-matics. His name is HAROLD GIBSON 3609 MOUNTAIN VIEW PASADENA CA 91107 818-795-7889. If you live out his way, I THINK he would be happy to help you. I ALSO THINK he would be happy to discuss your problem on the phone (California time.)



Lubrication Chart

LUBRICATE AT TACH ARROW POINT EVERY 1,000 MILES -- except de noted USA MARFAK (Seasonal Grade) unless otherwise specified See Page 3

UNDER HOOD




TABLE OF CAPACITES

	THE ST SHIP HE								
		CHANE	1RA HSM HSB HOR			PIFFOL	соотича	aus	
1	HOPE.	CASE	Aus.	Consta	Qreedrine	EIMIAL	With Heater	Willhout Because	TARK
1	.	Quant-	Querte	Prote	Plants	Piese .	Quart	Que to	Outlean
1	1956 Golden Howk	5	ж	i	3 🗱	וֹ נ <i>ב</i> ו	2414	23	•
1	1956-57, Others		9	2 %	3%	l 3:	18%	17	18
1	1953 55	٥	9%	2 %	3 1/4	3 ◆	18%	17 %	18

* 1937 Golden Howk and 1938 President Classic Sedan. 3% plats • Early 1935 Comm. below Serial No. 8387401, or 8843401 up to \$844301, 24) plane, all station wagons. 3

SIZE Recure 4 24 70 74

6 70-15, 1957 20= 7.10-15, 1957 6 70-15, Others 72 26 124 7 10-15, Others

TIME PRESSURES

₹Supplied Englisepeeds, 20 4 1934 President Classic Sedan. 10

FOR DETAILED PROCEDURES, REFER TO "SERVICE INSTRUCTIONS" SECTION PRECEDING THE LUBRICATION CHARTS

STUDEBAKER V-8 + 1953 thru 1957 CAMP CRUISER, PRESIDENT

MODEL IDENTIFICATION

Ŕ NUMBER; Blamped on plate attached to left South Bend, Maded | dont) | | Cation Numbers 4, 030, 003 Golden Hawl [Handlop]..... Searting Sevial Humbars 6.800,001 (Lot Angeles). Pool blags piller pool.

DAGINE NUMBER: Samperd on front sed of engine block between cylinder banks, directly beind water pump. Merika Engine Nember: (Seath West & Las Asquiss); K-1001 (Drandova), S-1001 (Ultramatic).

bustion character, or sharp edges in cylinder head, con-vert original Distributor Hall-Hook to large 183-4001E performance sees of cylindry below). If detention will present, implicin Timing that he retained slightly from standard 5° BTDC section. DETONATION CORPECTION (In Low Octors Asset): If detachation not caused by carbon deposits, 19945 com-

COMPRESSION PRESSURE: 120 ton. minimum at 150 RPM. Manifold variation between cylinders 10 lbs.

VACUUM READING: 18-21" at fulling speed,

MANIFOLD HEAT CONTROL. TO STOCKLID INTO THE DOLLARS DESCRIBE INC. THE PARTY OF THE PARTY DESCRIPED AND to seed of cold should against a position approximately 90° clockwise from cost another pin at some more learned room. haust plot. With beater valve to closed position, book VALVE TAPPET CLEARANCE: Noon (bydroule).

and IE; this valve to closed position, most examine than the discharged through the left analysis pipe.

IGNITION

-ENGINE "MISS" CORRECTION: May be caused by could be caused by could be control by the course of the country of the course of th

Moisture in Charitana Cept. Namers bechange drive and besently and dell two 1764, holes in groose ad-

BEST TO DATE THE

Cylinder - RIGHT BANK 2-1-6-8. LEFT BANK 1-3-5-1 FIRMS ORDER: 1-1-4-3-5-3-2-2

Spark Plug Gart, CCP Dist.
Spark Plays-Champton Ni-CTB. Jame. Torque to 30
R. Den. AOTÉ: Champton Ni-CTB can be used if colder plug denurable.

Igalisaa Curran, 2,2 aron, ading KOT Register-Aug-Lite PU-003. COIL: Ante-Line CAD-1004. 12 Yell

-COL RESISTOR NOTE: Resurer to consecrationeese with primary circuit between party) and roll fitters for 19 by-passed during canting by lead from starter Actional to coal.

DISTRIBUTOR: AMPLITY INTEGRAL OF INTERCOLE 12

* DIST PIBLIDE CONVERSION TO CORRECT DETOMA. TION (18J-000LCE: Install all parts familiand in Con-Volt. Santie pretier type.

5

it Car Plate, Contrast Beight Springs (Best & Hate) Scripts. Vacuum Spring, and small parts, Install new Tab-6001E numeplate (fumished in 113). Chack Auto-Kit. No. 6486408, pr follows: Distributor Bop. Contentor-Auto-Lite IBB-20151. Copecify- 25-28 mails & Vecuum Advance which should agree with (BJ-HONE specifications below.

Control Paint Set - Autor (Att 109-2018)

Bess 4 644 - 017 -

Branker Are Spiner Tennen-17-20 ozg. Refense-Causter-Clothade viewed from above

ğ Į, DIGGETS - speaking antiquestry Automotic Library . 10J. 4001E Peri Str 90 ă -

₽ Vector Speck Control: Auto-Lille. Integral type, • ; A 2275 8 3

. 7 1/3 2 Vectors (* of 30) Mecune Advance +BJ-4001C Eng. Degrees = ₽ : : Chart. Degrees. . : i

CHARLE OF A RO 74 H 5 . Vector Advance - | Bladding : CHITION TIMING Die Depres Charle Deligate i į ş .

from alundard 5" BTDC section if necessary to compet - DETONATION NOTE . THAIR MAY be INMARED BILLERIN disconnect recommendance page as certained descention. See Detendrien Correction.

Samuel 5. BTDC with menne iding at 550-600 RPM with transmission in neutral Before checking setting.

Treams Mark-Timing Indicator on their cover marked CAMBURETOR
CAMBURATE STATE TO THE STATE OF THE STATE S "d", "-5", "-10", "15", Align Index many (groove) on Moration damper with correct many on indicator,

PHANNEOLO FUEL DISTRIBUTION: COMMENT RIGHT borreit fred Cyl. 2-3-5-8. LEFT horneit 1-4-6-7. 14. Sering-A-14, turns oben Tum ecress our for TIDM. See "Carse MCFB 4-Bones" Codumers in Codu retion Section.

nonet histogre lide Speed-550:600 RPM with transmission in Deutral.

- OTHER DATA: See "Corns BCFB" Cornses in Con-Barneran Septian. Food Pomp Pondamen 186-5 line.

Cherrie Listege Adpairment (Ultremeter):

juster to cross-shaft rod in the center to cross-shaft lever (Supersades the lower hole specification used evertously), both locanits at adjuster released 4 or 5 tion with those in mide open position. Apply broken-block open choice water. theorement not at denoting wayne peter lever (nest of brokenseston), hold term mei, turn nömn be leift systädet stop, reposition laver on minnt so proper position som bedyre classy out. With adbened, disconnect exploration bell count and publication at bell crant, set also to provide 5, top at bell crans. Hold carbarator idla strem against its grop (M. gab at bell creat), Joseph overtraval and advently and adjust agrainat its 160p, straight bein agrains miljed septace travel wed essentible. Hold cross shaft lever lorward übbiem reur locknus agalası adjuster, then perure endestably man linkage, check for thre adding without bind, bring stephe to operating temperature, his supple speed in 400 RPK (selector level in "D" Drive posi of transmission case Taper and of 1844 month year telett bole is sell evalt und. Lock aut as erge-Until beat joint activitien combureton to bell crans nod Bree contact straight ridge. To correct, bossess have class HOME BALL 3 5


COST CHART TOO CONTRACT STATE OF THE PROPERTY STATE STATE Ĭ Ç. MUNICE SLEW FOR THE PERSON ---POTENTIAL PROPERTY PLACE NATIONAL PROPERTY NATION THE R. P. LEWIS CO. L. P. L. P

ИПЪМАПС ТИВОТПЕ ЦИКАВІ See First Statement of Statement Section. Generalise Copper Electric Lype. Dask Unit Statement Section. Test Unit Statement Section. See First Games. Georges" in Corbuminan Section. CARE, EQUIPMENT Feel Pump Menume . 176 S Ing.

CONTINUED ON MEXT PACE

125





HOW I SOLVED MY NOISY LIFTER PROBLEM ON MY 1956 GOLDEN HAWK By Frank Ambrogio

NOTE: I sent the following to Dwain Grindinger of Turning Wheel's Co-operator on December 21, 1988

Dear Dwain:

I wrote to you in January 1987 about the intermittant valve lifter noise problem I was experiencing in my 1956 Golden Hawk (Packard 352" engine with hydraulic lifters). I explained that after having the engine rebuilt, installing a second set of lifters, installing new push rods and rocker arms, the problem remained. You sent me Service Bulletin #314 and informed me of Service Letter #936 (which you did not have) which contained information on an oil pump relief valve tube kit identified as part number 6484613.

I contacted Phil Brown of Phil's Studebaker parts who contacted the Studebaker Museum and their combined efforts produced Service Letter 936. After my letter and your answer appeared in *Turning Wheels* "The Studebaker Cooperator", Richard Quinn (Almanac Editor), and William Stroud of Barrien Springs, Michigan, also sent me copies of Service Letter 936. Jim Maxey of Chandler, Arizona wrote and suggested running with the oil 1 quart over full and using Plymouth 318" valve lifters. I also recieved a call from Gary Siess of Dover, New Jersey who offered several alternatives.

I purchased the kit from Packard Farm and I had the kit installed on the oil pump. Although it made an improvement, it did not solve the problem.

While at the meet in Estes Park, I spoke to Robert Dietzler of Simi Valley, California who had solved a similar problem with his 56 Golden Hawk. Bob sent me information from Packards International Motor Car Club of Santa Ana, Ca.

Packards International claims that the problem is an inferior oil pump whose shaft was not properly designed to utilize a bearing causing the shaft to wobble and suck air into the oil stream. They also discovered that the pot metal cover plate on the bottom of the pump would swell under high speed operation thus allowing more air to be sucked in. They offered a redesigned pump to their members which they sold on an exchange basis.

I decided to buy the *Packards International* oil pump but I didn't want to give up my old pump and wait for the new one to arrive. I began searching for another oil pump and what follows is the real reason I am writing.

I checked my *Hollander* parts interchange manual and discovered there were two Packard oil pumps. Part number 6480508 was for the Packard 352" engine and part number 440729 was for all Packard V-8s except the 352" engine. This was the first time I had found a 56 Golden Hawk engine part that was different from a Packard V-8 engine part.

I began comparing pictures and part descriptions from my Studebaker and Packard parts books and found two differences. My oil pump had a flat plate on the bottom while the Packard had a larger plate. The Packard also had one part that my pump didn't have. It was listed as DRIVER - VACUUM PUMP.

After speaking with Joel Ray of *Patrician Industries* in Dearborn, Michigan, I discovered that the Packard had vacuum operated windshield wipers and therefore the larger bottom plate I had seen on the picture of the Packard oil pump was actually a VACUUM PUMP.


I had the engine rebuilt a few months after I bought the car in 1983 and suddenly I could vaguely remember the mechanic making some comment indicating that he had misplaced the oil pump. Could he have possibly put on another oil pump with a vacuum pump on it?

I checked my bill and found oil pump among the parts listed. Now, if the problem was air in the oil, and if my car had an oil pump with a vacuum pump on it, and the vacuum pump wasn't connected to anything, I reasoned that possibly the oil pump had been my problem all along.

I bought the Packard International oil pump which has a 3/4" bottom plate in place of the vacuum pump (the Golden Hawk pump had a 1/4" bottom plate). This bottom plate solves the problem of flexing at higher speeds, but I don't know what the Packard people do about their wipers. The oil pump that was taken off my Golden Hawk was, in fact, the one with the vacuum pump on the bottom. I have not heard any lifter noise since the new oil pump was installed.

Obviously the oil pump was the problem. I don't know if the vacuum pump was letting air in the system or if the pump was just bad to begin with, but after a 5 year battle, it is sure nice to be able to drive my car more than 20 miles.

Just thought you'd like to know I finally was successful and that there are a lot of great people in SDC who are willing to help.



29 PMLHS, CA 42277 619-367-1007

1956 STUDEBAKEN BOLDEN HANK OWNERS INFORMATION EXCHANGE CLUB DREAMIZED ON JAMUARY 1, 1989 FRANK J. ANDROGIO - HOWITOR

	FRANK J. AM	220510 - HOMITOR
EM MERGER MANE Um Address Pladme 4	SERJALO ENG DODY MUNTEN COLOR FS	COMMENTS
L FRANK J. AMBROSIO LOSS MODDING PINES MAY CASSELBERRY, FL 32707 LO7-179-8446	6032145 52920 \$7147-2195 A\$ MOCHA/BOESKEM Y 6011884 K1389 \$71K7-2280 DQ NOCHA/SHOWCAP WHITE M	FRANK HAD A HAND IN SETTING THE OIL FILTER RECAL REPARENCED BY JOHN BRICHETO OF AUTOSPORT IN TERMESSEE.
2 JERMIE A. FACKLAM 12360 W 1007W PL 1EMETA, KAMSAS 64215	\$032259 \$74K7-2869 Q\$ CORALTOME/SMONCAP MMITE	HMS EXTRA 352' ENGINE
3 JOHN RAISES RZ 801 240 PLATTSWOUTH NE 48049	A030390 54367- 545 AQ Royamay Red/Showcap Walite N	TRANS CONVERTED FACE AD TO DO IN 1967. ENGINE REPLACED 1352) IN 1966. CHACINE "GOLDEN HANK" ON TRANK.
U JAMES H. ACKMISHT 1810 M. ASTH ST. SAPULPA, DK 74066	6030654 Grey Primer	NEEDS HELP ON COLORS, NIREWG, VACUUM MOSES, PU MOSE, ARM NEST FOR FRONT DOOR, INNER FIN MOLOLMA STREPS.
5 JOHN WALCIS 954 MOLLADAY AVE. SAN FRANCISCO, CA. 96110 415-202-4446	ABGO37G S2448 57JK7 DD YELLOWSTGME/WEJMGHT DLACK	NORMALLY ENGINE NUMBERS (S) INDICATE AN AUTOMATIC SMILE IK FINDICATE OVERDAIVE. THIS IS AN S ENGINE NUMBER NUM OVERDAIVET JOHN'S COPY HIS ORIGINAL PRODUCTION DROFT SHOWED IN THIS NAV.
A TOM SWYDER ALL 2ND ST. S.E. PYERSVILLE, IDMA 52040 319-875-8772	603,7684 \$3825 563K7 00 GREY METALIC	ULIRA-HALIC MAS REPLACED WITH ISPO OVERORIVE, COLOR MAS BLACK. TOM MAS DESIGNED SOME MODY TO FRAME MOUNTS FOR HIS EAR. OPTIONS EMCLUME PB, PS, RADIO, CLOCK, HEATER.
7 RAMBY CAVOR1 R6 1 302 1570 ELMER W.J.08318 609-158-7385	4032553 \$4367-3089 MIDNIGHT MLACK 4030510 \$1147 \$4367-0745 OB AIR FORCE BLUE/MHCVE	IST CAR IS A PARTS CAR. 200 CAR IS BEING RESTORED.
8 CHARLES L. ADAMS P.O. BOE 3488 REDDING, CA 34049 914-243-7537	4800570 AD Green/And De	THE CRISEMAN EMBINE MEEDS A TOTAL RESULTO, EAR NOW HAS A PACKARD PARRIETAM 374 CIO.
9 GEOFFREY C. FORS 749 PACIFIC STREET ROWTEREY, CALIFORNIA 9394 408-626-0950	6000574 \$63K7-2838 AB 600ER/0HITE	PS, PW, PB, TENTED SCASS, PB RADIO, SU LAMPS, CLOCK, CRANK UP AMTERNA. ELECTRICAL SYSTEM SPECIALIST, MAS SOME NOS PARIS AVAILABLE FOR TRADE. NEEDS HELF ON ULIRA-NATIC.
10 JOE HALL 73430 RAYNONG OR 29 PMLMS, CA 92277	6032300 52410 AD AIRFORCE BLUE/SMONCAP WHT 6030689 52030	CAR 41 MAS COMVERTED FROM AD TO OD. CAR 02 MAS ORIGINALLY WHITE/MOCHA. CAR B3 MAS NO EMBINE OM PRANS BYT MAS DRIBINALLY AB, HAS PAINTED WINDSHIELD MOULDINGS. AND HAS VE EMBLEM FRONT

1-9

AB, HAS PAINTED WINDSHIELD MOULDINGS, AND HAS VE EMBLEN FROME

FEMDER SCRIPT IFST, JOE HAS RESTORED IST 'NO CARS HIMSELF, ZNO

GLENBROOK GREEN/SHALP MIT

LL791 STONE ALLL RD

513-385-9343

CINCIPMATE, OHIO 45247

1956 STUMEBAKER GOLDEN HANK ONNERS INFORMATION EICHANGE CLUB DREAMITED ON THROWAY 1, 1989 FRANK J. AMERICANO - MONITOR

	N MENDEN MANE N ABORESS	SERIALO ENS OCOV MURT Colur	RN FS	COMMENTS
	PHONE D			
		6033288 Smokeap mhite/romany red T	44	CAR 35 GOING TO JOE'S BROTHER IN SENTUCKY AROUND HARCH 89. 17 YEARS AS A MECHANIC AND CAM HELP WS WITH ENGINE, IRANS AND OTHER PROPLEMS.
11	CLAUDE E. SEVON 19770 SE 290TH ST. AUNUMU, MASH, 98002 206-735-3127	6B00274	90	EMBINE MAS BEEN REPLACED NITH A PACKARD CLIPPER I SAME ENGINE A BIFFERENT VALUE COVERSH. FLOOR SHIFT ON TRANS. HAS HAD HADE AND INSTALLED FRAME SPENETHENERS WHICH SIGNIFICANTLY RESULTED FRAME FLETCHE, BUILL A REAR ATLE PULLER FOR 60 CENTS AND HAD ARTICLE PLBLISHED IN SKINNED KNUCKLES HABAZINE IN JAN 80. DOES ALL HIS DWN NORK.
LZ	JOHN W. WILLIAMS 11461 U.S. 27 WEST WILLIAMSPORT, DHID 43164 619-984-6803	6031748 Yell ows 10me/smoncap white	AB	SW,000 MIRES ON OPIGERAL ENGEME AND MARKSHISSION, JOHN HAS STORED THE 7:10:03 TIRES AND WHEELS AND HOLMHED ROPAR DUAL PARTERN WHEELS AND 725/75 DIS TIRES WHICH HE SATS HAVE VASTLI IMPROVED THE HANGLING, BOUGHT CAR FROM CRISINAL DWINER IN 1967.
13	LEWIS DANGUMANG 3505 N. GREGORY DR. TUCSON, ARTIZONA 05765 602-743-045)	ACTROAY Pink/mailte	40	CAR HAS BEEN REPAINTED OLL WHITE. MEEDS CONFLETE RESTORATION WHICH LEWIS WILL DO. MEEDS HEADLINER PRWELS/PETAINERS, FULL WHSEL COVERS.
14	CARL P. EURWER 2377 REBALETON DINTER PARK, FL 32792 407-444-0478	6032545 K3261 SAJK7-1887 6010/001116	00	CAR WAS BEEN UN THE FAMILY \$1900 MEN. ENGINE REPUBLIT. REPAINTED BOLD/MH21E, MOT SAME AS DATE AND SUMBLIN GOLD/SAGNCAP MH2TE.
	JOHN P. GARES 51425 ARCH ST. GRANGER, IMPIANA 46530 219-277-4137	PASEMANHESE 24184-3254	00	HAS ESTRA PACEARD ENGINE. DOUGHT CAR IN 1985 WITH \$4,960 MILES.
	HOMARD R. HIMSHAM RI. 2 NOT 221 WELVIDERE, TH \$7306 613-967-2006	6777797 \$3205 \$6JK7-2576 (HOCHA/DOE5K K	k a	CAP WAS CONVERTED TO 3 SPD FLOOR SHIFT. NEEDS HELP ON HEADLINER AND PLASTIC HEADLINER BOWS.
	BOU EDMANOS 11923 McCOANICK AB C-17 JACKSONYILLE, FL 32225 104-	6033090 568x7-3642 0 BLACK 1)a	CAM HAS 16EN AEPAJUTED DLACK (MAS ONIS)HALLY DLUE/MHITE, MAS A Continental Masel.
	PATRICX SCHAFER 7000 SIGNAL PHILD, CA 95466 707-895-3722	4800501) MOCHM/DOESK III	10	-
	RICHARD & ROSE POE	6032793 36JM7-3324 0	ŀ	CAR MAS BLACK AND MAD NO ENGINE OR INTERIOR WHEN PURCHASED BY

RE SUMPLON GOLD AND TELLOWSTONE.

ROSEPUBLISHOOM WHITE

THE POES. IF WON HAS A 1962 289' ENGINE, + BPL, + SPEED FOR +

6.T. AND BUCZET SEATS. THEY ARE WORKING ON THE BODY AND IT WILL

1954 STUDERARER GOLDEN HAWY CHAMERS INFORMATION EXCHANGE CLUB OMERNITED ON DAMMARY 1, 1989 FRANK J. ANDROSCO - HOWLTON

FS

HER MEHBER HARE MIR ADDRESS

SERCALO EMS BODY WAR ION COLOR

CONNERIS

PHOME B

995 300 BIETZLER

4989 LEEDS ST.

805-527-1642

SIME VALLEY, CA 43063

20 JOHN W. JERNELLE AT (BDJ 227 EGGLESION, VA. 24084 703-921-2121

4777737 562K7-3587 ## GREEN/SHOWCAP WHITE

> SENT DOB ON INVITATION TO JOIN, AS YET ME HAS NOT RESPONDED. BOB HAD MIS DIL PURP MODIFIED BY FACKARD INTERNATION TO FIX HIS VALVE LIFTER PROPLEM.

496 METTY C. FRENCH F.O. 801 492 COCHRAM, GEORGIA 31014 912-934-7914

METTY GAMES A 1956 GH. SENT HER AM INVERATION TO JOIN, HAS NOT RESPONDER.

347 DOW M. GERURN 273 SHEDIAC ROAD MONCTON, N.D. EIA 255 CANABA

MOCHA/DOESCIA

SEMI OOM AM INVESTITION TO JOSM. HAS NOT RESPONDED.